



THIS CKT LOOKS TO BE A STARTUP CKT AND SHOULD BE CONNECTED TO B+ NOT B+

SUSPECT THIS SHOULD BE CONNECTED TO B++ ALSO NOT B+

THIS CONNECTION SHORTS THE PASS TRANSISTORS, CANT BE RIGHT

THIS IS WHERE FLOATING RETURN TIES TO CHASSIS GROUND

REGULATOR BOARD